



for windows



store and transport
in a frost free area



store in a cool place



cleaning of
equipment with
water



shake well before
use

Pflegemilch für Fenster

Product description Waterbased maintenance milk to protect and refresh weathered paint surfaces on windows. Regular use prolongs the renovation intervals.

- water and dirt resistant
- quick drying
- easy to apply
- good weather resistance
- good colour and gloss refresher

Colour Colorless

Gloss level Gloss, matt

Binder type Watery polymer

Packaging 250 ml

Processing The paint surface which should be maintained has to be cleaned thoroughly with a suitable household cleaning agent and afterwards with the special cleaner for deeper cleaning. When the surface is fully dried the maintenance milk is applied with a sponge quickly, but evenly on the paint surface. Before use of the maintenance milk the bottle has to be shaken intensely.

The matt maintenance milk is for matt and semi-matt surfaces, the glossy maintenance milk should be used for satin-gloss and glossy surfaces.

Consumption Approx. 20 ml/m²

Thinning Do not thin down

Application temperature +10 - 30 °C for substrate, air and material at approx. 60 % R.H.

Drying times Drying at 23 °C / 50 % R.H.

Dust dry: after approx. 10 - 20 minutes

Cleaning of equipment Clean directly after use with water, if needed with washing up liquid or with ST 830.

Storage The minimum storage stability of sealed containers is 2 years.

Storage temperature: +5 - +30 °C.

After ending of the storage time the product still can be usable, but some attributes may vary from new product. Therefore such over-stored product has to be applied with special attention.

Opened cans must be sealed correctly! Store in a cool but frost-protected area.

Disposal Only residue emptied cans can be disposed via recycling. Liquid wastes must be disposed of according to national regulations or according to EU-disposal key 08 01 12.

Hazard identification In accordance with EC guide lines - Material safety data sheet, point 15.

Warning Before use, read the identification and product information. Even when working with low emission products one should take care of the customary protection measures.

General instructions Through the application of maintenance milk, painted surfaces obtain the original freshness. With regular use (1-2 yearly in spring and autumn), the durability of the coating system rises and maintenance periods can be extended. Defect coating systems cannot be repaired with maintenance milk. The correct products are referred to on the technical data sheets.

Relevant information The gloss level of the surface might be changed by the maintenance milk.

Coating recommendation Before the maintenance coating, the surface has to be sanded thoroughly and cleaned with the special cleaner. The maintenance coat should be carried out Sikkens renovation products.

All details on our products contained in this publication do not represent details of the quality of the goods. The quality, suitability, qualification and function intended use of our goods shall be determined exclusively in accordance with the product descriptions based on the respective sales agreements. In each case, deviations typical of the sector shall be admissible, unless agreed in writing otherwise. All details correspond to today's state of technology. We make no claim as to the completeness of the stated coating installations; they are stated merely as possible examples. Due to the large number of substrates and object conditions, the buyer/user shall not be released from his/her obligation to check our raw materials in a workmanlike manner for their suitability for the intended purpose on his/her own responsibility subject to the respective property conditions and process these in accordance with the respective state of technology. In other respects, our standard terms and conditions of sale apply. Upon the appearance of a new edition, this publication shall lose its validity.

Akzo Nobel Industrial Coatings Ltd Unit 4a, Mercer Way, Shadsworth Blackburn, Lancs, BB12QZ
Bus Pk
Akzo Nobel Industrial Coatings Ltd Unit 4a, Mercer Way, Shadsworth Blackburn, Lancs, BB12QZ
Bus Pk
Akzo Nobel Wood Coatings GmbH Düsseldorf StraÙe 96-100 D-40721 Hilden

UNITED KINGDOM

Rep of IRELAND

GERMANY

Tel. +44 1254 687950

Tel. +35 (0) 21 4220222

Tel.: +49-2103-77-800

Fax. +44 1254 687960

Fax. +35 (0) 21 4220205

Fax: +49-2103-77-577